



PT8902

High Impact Urethane For Prototype Parts

DESCRIPTION

PT8902 is a unique two-component urethane casting system that has very high cured properties which allow it to produce extremely durable parts and shapes that have very good heat resistance. PT8902 has a notched Izod Impact strength greater than 2.0! It also has a Glass Transition Temperature (Tg) of 213°F. This material will make tough parts!!

The pot life of 6 - 7 minutes and very low mixed viscosity of PT8902 make it very easy to handle and cast by hand pour or machine casting techniques. It's low viscosity fills thin sections and complicated shapes with ease. The cured material is very tough, and it can be demolded from the toughest mold configuration without breaking. The natural white color of PT8902 can be easily tinted or pigmented for a broad range of colored parts. Try PT8902 on your most difficult parts and see how easily it produces very successful castings that are tougher than any previously available material.

PRODUCT SPECIFICATIONS

	PT8902 Part A	PT8902 Part B	ASTM Method
Color	Lt. Amber	Clear	Visual
Viscosity, centipoise	80 - 100 cps	650 cps	D23932
Specific Gravity, gms./cc	1.17	1.11	D1475
Mix Ratio, By Weight	100 Parts A to 50 Parts B		PTM&W
Pot Life, 4 fl. Oz. Mass @ 77°F	6 - 7 minutes		D2471

HANDLING and CURING

The two clear components of PT8902 form a tough, white, opaque solid when cured properly. The material needs heat to effect a proper cure. At room temperature, the white color change does not occur, and the optimum physical properties are not obtained. You must give this material some heat to initiate the proper cure structure, and achieve correct cross linking which is indicated by the color change.

The mixed PT8902 should be poured into a warm mold (heated to at least 125°F) and given an initial oven heat cure before demolding. The material can be demolded after a minimum of 2 to 3 hours at 150°F to 160°F, and then the cure can be completed out of the mold. If the part has relatively thick wall sections and a flat surface it can be positioned on, then it can be post cured unsupported in the oven. However, if there are thin walls or standing sections, the part should be supported on a fixture in the oven for the post cure. It is advisable to support the part in the mold or on a fixture all cases for repeatable good results.

The type and extent of post cure will be determined by the eventual operating parameters of the part. With the proper cure, PT8902 achieves very high impact strength as well as very good heat resistance. The high impact strength properties are achieved with even a low to moderate post cure, but the ultimate Tg (heat resistance) is not achieved unless a proper elevated temperature post cure is utilized.

The ultimate cured properties, as listed in this bulletin, were obtained by the following curing cycle: The mixed material was poured into a mold heated to 130°F, and allowed to gel in a pressure chamber. The mold was placed in an oven and cured for 2 ½ hours at 150°F. The mold was removed from the oven, allowed to cool to 100°F, or below, and the part was demolded without distortion. The part was then cured overnight at 180°F, and the samples were tested 7 days after casting.

Here are the results of various cure schedules, to aid in selecting one to obtain the proper cured properties for the intended application:

Handling & Initial Cure Details	Post Cure Used	Izod	Tg	E'
** Pour into Mold Heated to 130°F, Cure 2-2½ hr @ 150°F, Cool, Demold	Overnight @ 180°F	2.1	213°F	193°F
Pour into Mold Heated to 130°F, Cure 2-2½ hr @ 150°F, Cool, Demold	After 7 Days @ Room Temp.	2.04	192°F	159°F
Pour into Mold Heated to 130°F, Cure 2-2½ hr @ 150°F, Cool, Demold	Overnight @ 150°F	1.72	205°F	186°F
Pour into Mold Heated to 130°F, Cure 2-2½ hr @ 150°F, Cool, Demold	2 hours @ 180°F	1.6	205°F	184°F
Pour into Mold Heated to 130°F, Cure 2-2½ hr @ 150°F, Cool, Demold	2 hours @ 150°F	1.5	195°F	174°F
Pour into Mold Heated to 160°F, Cure 1 hr @ 160°F, Cool, Demold	After 7 Days @ Room Temp.	2.1	197°F	175°F
Pour into Mold Heated to 160°F, Cure 2 hr @ 160°F, Cool, Demold	4 hr @ 160°F, then 7 Days @ R.T.	2.1	206°F	187°F

**** Recommended**

PT8902 High Impact Urethane, Page 2

TYPICAL MECHANICAL PROPERTIES

	PT8902 A/B	ASTM Method
Mix Ratio, By Weight	100 : 50	PTM&W
Color	White	Visual
Mixed Viscosity, centipoise	495 cps.	ASTM D2393
Working Time, 4 fl. Oz. Mass, @77°F	6 - 7 minutes	ASTM D2471
Cured Hardness, Shore D	85 Shore D	ASTM D2240
Specific Gravity, grams, cc	1.15	ASTM D1475
Density, lb./cu. Inch lb. / gallon	.0417 9.6 lb. / gallon	ASTM D792
Specific Volume, cu. in./lb.	24.0	ASTM D792
Tensile Strength, psi	10,010 psi	ASTM D638
Elongation at Break, %	21.6 %	
Tensile modulus, psi	371,155 psi	
Flexural Strength, psi	15,574 psi	ASTM D790
Flexural Modulus, psi	386,612 psi	ASTM D695
Compressive Strength, psi	11,943 psi	
Compressive Modulus, psi	357,510 psi	
Izod Impact Strength, ft.lbs./inch of Notch, Method A, Notched	2.1	ASTM D256
Glass Transition Temperature, DMA: T _g (Peak) E' (Onset)	213°F 193°F	ASTM D4065
Heat Deflection Temperature, @ 64 psi Load	190°F	ASTM D648
Coefficient of Thermal Expansion, Range 50°C to 100°C	6.09 x 10 ⁻⁵ in/in/°F	ASTM

PACKAGING WEIGHTS

	Gallon	Pail	Drum
PT8902 Part A	8 lb.	40 lb.	460 lb.
PT8902 Part B	4 lb.	20 lb.	230 lb.
Kit	12 lb.	60 lb.	890 lb.

SAFETY and HANDLING

PTM&W urethane products are made from raw materials carefully chosen to minimize or even eliminate toxic chemicals, and therefore offer the user high performance products with minimum hazard potential when properly used. Generally, the PTM&W urethane resins and hardeners will present no handling problems if users exercise care to protect the skin and eyes, and if good ventilation is provided in the work areas. However, breathing of mist or vapors may cause allergenic respiratory reaction, especially in highly sensitive individuals. As such, avoid contact with eyes and skin, and avoid breathing vapors. Wear protective rubber apron, clothing, nitrile rubber gloves, face shield or other items as required to prevent contact with the skin. In case of skin contact, immediately wash with soap and water, followed by a rinse of the area with vinegar, and then a further wash with soap and water. The vinegar will neutralize the hardener and lessen the chances of long term effects. Use goggles, a face shield, safety glasses or other items as required to prevent contact with the eyes. If material gets into the eyes, immediately flush with water for at least 15 minutes and call a physician. Generally, keep the work area as uncluttered and clean as possible, and clean up any minor spills immediately to prevent accidental skin contact at a later time. Keep tools clean and properly stored. Dispose of trash and empty containers properly. Do not use any of these types of products until Material Safety Data Sheets have been read and understood.

PT8902 Bulletin / ZW-38 / 072604-C2



PTM&W Industries, Inc.

10640 S. Painter Avenue Santa Fe Springs, CA 90670-4092
 562-946-4511 800-421-1518 FAX: 562-941-4773
 Visit Us At: www.ptm-w.com Send Questions To: info@ptm-w.com